

The “Department Head Reports” from DOT for the [July 4, 2023](#), are listed below:

- DOT crews completed repairs at post mile 6.3 at Lower South Fork Road, and re-opened the same road at post mile 10.5, which restored vehicular access to the three residences beyond the slide, while they continue with the more permanent repairs of the slump. Soil material deposited on Hyampom Road, due to slope slides after the recent storm, is also removed and placed adjacent to the Hyampom Airport, as shown in the attached photos.
- Tullis, Inc. finished paving the bus parking area and access roads. The water line is complete, and electrical improvements are in progress. Installation of fencing and gates is also in progress. Attached are photos of the paving operations.
- In addition to storm damage repairs, DOT crews are also busy with routine maintenance operations, including repainting airport runway markings, using the county’s new paint truck as shown in the attached photo.

If you have any questions please let me know.



**Loading and hauling off slide material in multiple locations, along Hyampom Road**



**Disposal site adjacent to Hyampom Airport for slide material from Hyampom Road & cut from Lower Southfork**



**Opening up Lower Southfork Road at PM 10.5 and starting the cut for a new road**



**Paving operations (contractor) for the new Transit bus parking lot adjacent to Lance Gulch Road**



**County crews are paving a centerline stripe at the Trinity Center Airport**